








Very forward block
Failure 1/19





Very forward block (1 of 3)
Failure 1/19




Midships block (2 of 3)
Failure 1/19

A close-up photograph of a blue-painted metal beam resting on a stack of wooden planks. The planks are supported by a rusty metal beam. The text "AFT blocking (3 of 3)" is overlaid on the image.

AFT blocking (3 of 3)



Significant corrosion on all screwjack pins



Fwd Starboard jack and oilcanning



1/19 Pin
Bending & plate
compressed



12/29 Pin
Not Bending




Fwd Starboard jack and oilcanning



Fwd port jackpad and oilcanning



Fwd port jackpad and oilcanning



Cracking
Tab

Cracking
Tab





